
City of Baltimore Wet Smoke and Dyed	Page 1 of 2	
Sewershed: Gwynns Falls	Company: Savin	Date: 4/21/2009
Test to be performed: Smoke Dyed Water X	Ground Condition: Dry ✓ Damp □ Wet □	Supervisor: <u>JAW</u>
Manhole_ID: S03K_015MH	Test ID: <u>D1032-002005</u>	Notification Made: NA (Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Manhole	S03K013MH
0			Start of Survey	
0			Water Level	
8			Dye Test Visible	@ IR, 1/8 GPM
8	08		Infil Runner	@ jt
11.80000019	09		Infil Runner	@ IR, 1/4 GPM
14.69999981			Dye Test Visible	@IR, 2 GPM
14.69999981	08		Infil Runner	@ jt
17.70000076			Dye Test Visible	@ IR, 3 GPM
17.79999924	09		Infil Runner	@ jt
23.29999924			Abandoned Survey	NO MORE DYE INFIL IN SEWER

City of Baltimore Wet Smoke and Dyed	Page 2 of 2	
Sewershed: Gwynns Falls	Company: Savin	Date: 4/21/2009
Test to be performed: Smoke Dyed Water X	Ground Condition: Dry ✓ Damp □ Wet □	Supervisor: JAW
Manhole_ID: S03K_015MH	Test ID: <u>D1032-002005</u>	Notification Made: NA (Residents, Fire, 311)